

Technical Service Bulletin


Source: Leece-Neville Heavy Duty Systems Division - Arcade, NY USA


Date: August 20, 2009

Bulletin No: TSB-1139

Models: 8SC


Subject: Wiring diagram





Models covered: 8SC3009ZA 8SC3009ZAC 8SC3014U 8SC3015U 8SC3019U 8SC3029Z 8SC3068V 8SC3068VC

Note: AC terminals located beneath the voltage regulator.



Important: The information contained in this bulletin is intended for use by trained, professional technicians who have the proper tools, equipment, and training to perform the required maintenance described above. This information is NOT intended for 'do-it-yourselfers', and you should not assume that this information applies to your equipment. If you have any questions regarding this information please visit our website at www.prestolite.com, or contact our technical service department at: