

[illegible]

Exploded view diagram of a mechanical assembly. The diagram shows the following components and their assembly sequence:

- Part 1:** A long shaft with a gear and a pinion.
- Part 2:** A pinion.
- Part 3:** A small washer or spacer.
- Part 4:** A small washer or spacer.
- Part 5:** A large cylindrical component, likely a housing or cover.
- Part 6:** A small pin or screw.
- Part 7:** A gear.
- Part 8:** A small washer or spacer.
- Part 9:** A small washer or spacer.
- Part 10:** A pinion with a gear ratio of $i=2.64$.
- Part 11:** A pinion with a gear ratio of $i=2.33$.

Assembly instructions:

- REFER TO Fig.1** (indicated by a line pointing to the housing assembly).
- REFER TO Fig.1** (indicated by a line pointing to the gear assembly).

[illegible]

Fig.3. OUTPUT SHAFT




Fig.3. OUTPUT SHAFT

[illegible]

