


LAYOUT DIAGRAM - DC/AC CONVERTER



Reference	Designation
1	DC/AC converter
2	Copper Bar (Negative terminal)
3	Fuse - 300A
4	Voltmeter
5	Earthing plate
6	Remote control
7	Breaker
8	Service batteries positive isolation switch
9	Entrance (AC sockets)
10	Outlet (Electrical panel)